


LEGEND

---	DISTURBED AREA BOUNDARY
---	RECLAMATION CONTOUR
---	WILLOW CREEK RECLAMATION CONTOUR
---	(GSD-1) RECLAMATION CHANGE
---	(GSD-1) OPERATIONAL DRAINAGE DITCH REPAIRED AFTER RECLAMATION
---	(GSD-1) WILLOW CREEK RECLAMATION DITCH
---	(GSD-1) OPERATIONAL CULVERT REPAIRED AFTER RECLAMATION
---	(GSD-1) WILLOW CREEK RECLAMATION CULVERT
---	RECLAMATION PREPARATION AREA, UPLAND SEED MIX, TABLE 5.5-2 (DEEP GOUGING AND MULCHING)
---	INDUSTRIAL POSTMINING LAND USE BOUNDARY (4.2 ACRES)
---	PROCESS WATER POND
---	PROCESS WATER, HELPER CITY
---	SANITARY SEWER, HELPER CITY
---	SOIL PIT SAMPLING LOCATION

NOTES:

1. 49.10 ACRES OF WILDLIFE HABITAT BETWEEN THE INDUSTRIAL POSTMINING LAND USE BOUNDARY AND THE DISTURBED AREA BOUNDARY.



XREF'S

6-UT0917.DWG FINAL-WORK BASE-FINAL-
OPS.DWG
6-UT0917.WILLOWCREEKBASE-20.DWG

REVISION/HISTORY

REV	DATE	DESCRIPTION
01	4-93	
02	12-03	
03	05-04	
04		
05		
06		
07		
08		
09		
10		
11		
12		
13		
14		
15		
16		
17		
18		
19		
20		
21		
22		
23		
24		
25		
26		
27		
28		
29		
30		
31		
32		
33		
34		
35		
36		
37		
38		
39		
40		
41		
42		
43		
44		
45		
46		
47		
48		
49		
50		
51		
52		
53		
54		
55		
56		
57		
58		
59		
60		
61		
62		
63		
64		
65		
66		
67		
68		
69		
70		
71		
72		
73		
74		
75		
76		
77		
78		
79		
80		
81		
82		
83		
84		
85		
86		
87		
88		
89		
90		
91		
92		
93		
94		
95		
96		
97		
98		
99		
100		

EarthFax Engineering, Inc. Engineers/Scientists	RECEIVED MAR 22 2004 DINWIDEN & SONS INC. OF UTAH
--	--

PLATEAU MINING CORPORATION	WILLOW CREEK MINE PREP. PLANT AREA AND REFUSE PILE RECLAMATION TOPOGRAPHY AND TREATMENT MAP
847 NW HIGHWAY 191 HELPER, UTAH 84526 PHONE: (435) 472-0475	DATE: DEC 2003
CHECKED BY: JOHNNY PAPPAS DATE: DEC 2003	DATE: DEC 2003
DRAWING NO. 6-UT0917.DWG/FINAL-WORK EX3.4-12 J.DWG 11-20-03	DATE: DEC 2003
EXHIBIT 3.4-12	

